



- **Industrial Products**
- Headgear and face shields
- Hard cap and hat brackets
- Sun Shields-UV protection
- Knee Shields
- Chemical goggles
- Arc Flash Products
- **Tactical Products**
- Helmet riot shields
- Body shields
- Goggles
- **Fire Fighter Protection**
- Structural goggles
- Wildland goggles
- **Motor Sports**
- Helmet shields
- Bubble Goggle

Fire Goggle A-TAC Model 510-E

ISO 9002
Registered
Quality



Instructions for attaching A-TAC Model 510-E and A-GC to your Helmet

Fig. 1



Fig. 2



Assembly

Install the A-GC Clips on your helmet by:

1. Place the Goggle into the as worn position with the strap crossing the brim Fig. 1.
2. Press the clip over the strap and, capturing the strap with the clip. Fig. 1
3. The goggle may be stowed in the front or at the rear of the helmet. When wearing the helmet you simply pull the goggle forward and down, lightly tighten the straps if necessary. Loosen the strap tension by pushing the tabs forward. Fig. 2
4. **Note: Goggle may be worn directly on your head and not attached to the helmet.**

Cleaning and Maintenance Instructions

Clean and inspect after use. Clean with a damp cloth unless heavily soiled. Should further cleaning be required, clean with mild soap and water, pat dry. Disassemble if required, for cleaning or inspection. Inspect and replace any damaged or worn components.

Warning

Failure to follow these instructions can result in permanent impairment of sight or other serious personal injury.